



# Department of Education

## School Watching Activity Report

School Name	Talipapa ES
School ID	104431
Date	13 January 2023

### OVERALL REPORTED HAZARDS



### Hazard

Description	Quantity
Broken door knobs	1
Broken window	2
Broken/dilapidated ceiling	1
Busted light bulb	1
Detached/peeled off GI sheet	1
Dripping ceiling	1
Exposed electrical wires	1
Flooded area	1
No posted emergency hotline numbers	1
No ramps for elevated school buildings or other facilities	1
Open/clogged canals	1
Plants mounted on the building railings	1
Slippery pathway	1
Stagnant water	1
Unlabeled chemicals and liquids	1

### Capacity

Description	Quantity
-------------	----------

### Others

Description	Quantity
-------------	----------



# Department of Education

## School Watching Activity Report

### REPORTED HAZARDS PER STATUS



### REPORTED HAZARDS PER TYPE



Hazard	Timeframe		Type	Status
	Start	Until		
Broken door knobs	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
Broken window	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
Broken/dilapidated ceiling	13 Jan 2023	31 Mar 2023	Major Hazard	Not Yet Started
Busted light bulb	13 Jan 2023	31 Mar 2023	Minor Hazard	Not Yet Started
Detached/peeled off GI sheet	13 Jan 2023	31 Mar 2023	Major Hazard	Not Yet Started
Dripping ceiling	13 Jan 2023	31 Mar 2023	Major Hazard	Not Yet Started
Exposed electrical wires	13 Jan 2023	28 Feb 2023	Major Hazard	Not Yet Started
Flooded area	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
No posted emergency hotline numbers	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
No ramps for elevated school buildings or other facilities	13 Jan 2023	31 Mar 2023	Minor Hazard	Not Yet Started
Open/clogged canals	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
Plants mounted on the building railings	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
Slippery pathway	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started



# Department of Education

## School Watching Activity Report

Stagnant water	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started
Unlabeled chemicals and liquids	13 Jan 2023	28 Feb 2023	Minor Hazard	Not Yet Started

Capacity	Timeframe		Type	Status
	Start	Until		

Other Hazards	Timeframe		Type	Status
	Start	Until		



# Department of Education

## School Watching Activity Report

### School Head Narrative

---

Talipapa Elementary school conducted school watching and hazard mapping last January 13, 2023. The activity was participated by Ten Batang Empowered and Resilient Team members. Using the School Watching Application, they assessed the grade-V classroom and hallway to check the hazards and risk. A few hazards were identified such as broken windows, broken, dilapidated and dripping ceilings, exposed electrical wires and etc. After identifying the hazards, we identify each item as minor or major hazard along with the plan action and timeframe.

Submitted By:	
_____	_____
Super Administrator	Date
Reviewed By:	
_____	_____
Princess Moises	Date
Approved By:	
_____	_____
Harron Dave Antonio	Date